



CR 2/11

# BOREHOLE SECTION SHEET

Date **SEPTEMBER** 19 **60**

CONTRACT NAME: **MILL HILL** TQ29SW REPORT NO. **8-212/10**  
 Bored for: **War Office** 112  
 Address: **Chessington, Surrey.** 2417 9214  
 Address of Site: **Hittay Hill** County:  
 District or Town: **Mill Hill**  
 Standing Water Level: **6"** below surface Dia. of Borehole: **7 1/2"** Inches.  
 Water Struck (1) (2) (3)  
 Ground Level: **325.4** Boring Commenced: **25.8.60** Boring Completed: **26.8.60**  
 Special Remarks:

Jar Samples: **11054-0'0"; 11055-2'0"; 11056-7'0"; 11057-12'0"; 11061-17'0"; 11062-22'0"; 11063-26'0"; 11066-29'0"-water.**

Core Samples: **11056 - 3'0"-4'6"; 11060 - 13'0"-14'6"; 11063 - 23'0"-24'6"; 11065 - 28'0"-29'0"**

Bulk Samples: **11057 - 4'6"**

DESCRIPTION OF STRATA	Thickness		Depth Below Surface	
	Feet	Inches	Feet	Inches
The descriptions are given in accordance with the Civil Engineering Code of Practice No. 1 "Site Investigations." No responsibility is accepted for these descriptions and clients should examine the samples submitted.				
No. <b>2</b> Boring				
<b>Top soil</b>	<b>0</b>	<b>6</b>	<b>0</b>	<b>6</b>
<b>Fine brown clay.</b>	<b>3</b>	<b>6</b>	<b>4</b>	<b>0</b>
<b>Claystone</b>		<b>9</b>	<b>4</b>	<b>9</b>
<b>Fine stiff brown clay</b>	<b>25</b>	<b>3</b>	<b>30</b>	<b>0</b>
TOTAL FROM SURFACE ...				
	<b>30</b>	<b>0</b>	<b>30</b>	<b>0</b>