



# BOREHOLE SECTION SHEET

Date: **20.8.60** 19 **60**

CONTRACT NAME: **NEEL HILL**

REPORT No. **8.222/10**

Bored for: **War Office**

**TQ29SW**

Address: **Chesham, Surrey.**

**114**

Address of Site: **NEEL HILL**

**24179214**

County:

District or Town: **NEEL HILL**

Standing Water Level: **below surface**

Dia. of Borehole: **7 1/2** Inches.

Water Struck (1) **None** (2) (3)

Ground Level: **303.6** Boring Commenced: **20.8.60**

Boring Completed: **20.8.60**

Special Remarks:

Jar Samples: **11075 - 1'0"; 11076 - 2'0"; 11002 - 7'0"; 11003 - 10'0";  
11005 - 17'0"; 11007 - 22'0"; 11008 - 27'0"**

Core Samples: **11000 - 4'0"-5'0"; 11003 - 10'0"-11'0"; 11005 - 17'0"-18'0";  
11008 - 26'0"-30'0".**

Bulk Samples: **11001 - 6'7"**

DESCRIPTION OF STRATA	Thickness		Depth Below Surface	
	Feet	Inches	Feet	Inches
The descriptions are given in accordance with the Civil Engineering Code of Practice No. 1 "Site Investigations." No responsibility is accepted for these descriptions and clients should examine the samples submitted.				
No. <b>4</b> Boring				
<b>Top Soil</b>	<b>1</b>	<b>0</b>	<b>1</b>	<b>0</b>
<b>Thin Brown Clay.</b>	<b>3</b>	<b>3</b>	<b>4</b>	<b>3</b>
<b>Clay Stone</b>		<b>6</b>	<b>6</b>	<b>9</b>
<b>Thin stiff Brown Clay</b>	<b>23</b>	<b>3</b>	<b>30</b>	<b>0</b>
TOTAL FROM SURFACE				
	<b>30</b>	<b>0</b>	<b>30</b>	<b>0</b>